




Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
FURNISS AVENUE	O/S 43-45	TR: Felling. Decay .	Significant stem and scaffold decay	Prunus Kanzan	Plant o/s 39-41 in verge.	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 92	TR: Felling. Decay	Stem cavity, poor condition	Sorbus aucuparia sp	Plant in verge o/s 90-92	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 98-98a	TR: Felling: Decay	Significant stem decay and dieback of crown and scaffold	Sorbus aucuparia sp	Plant in verge in same position o/s 98	Sorbus intermedia 'Brouwers'
FURNISS AVENUE	O/S 49	TR: Felling-	Stem ripped out, poor structural condition	Prunus Kanzan	plant in verge in same position o/s 49	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 6	TR: Felling	F/W cracking by shallow rooting	Prunus Kanzan	Plant in verge o/s 6-8 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 12	TR: Felling	Extensive stem bark necrosis, poor specimen	Prunus Kanzan	Plant in verge o/s 12 (same position as felled tree)	Crataegus 'Pauls Scarlett'
FURNISS AVENUE	O/S 24	TR: Felling	Extensive stem bark necrosis and f/w damage	Prunus Kanzan	Plant in verge o/s 24 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 34	TR: Felling	Weak union at crown break	Prunus Kanzan	Plant in verge centrally o/s 34-36 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 40	TR: Felling	F/W mounding by extensive lateral rooting	Prunus Kanzan	Plant in verge o/s 40 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 58	TR: Felling	Extensive stem bark necrosis, and f/w cracking	Prunus Kanzan	Plant in verge o/s 58 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 76	TR: Felling	Topped in past, stem wounding, poor specimen	Prunus Kanzan	Plant in verge o/s 76 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 114	TR: Felling	Extensive Coriolus versicolor stem decay	Sorbus aucuparia sp	Plant in verge o/s 114 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 118	TR: Felling	F/W mounded and cracked	Prunus Kanzan	Plant in verge o/s 118 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 132	TR: Felling	Stem wounded and f/w cracked	Prunus Kanzan	Plant in verge o/s 132 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 131	TR: Felling	Ganoderma sp. basal decay and stem wounding	Prunus Kanzan	Plant in verge o/s 131 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 93	TR: Felling	Extensive stem decay, very poor specimen	Sorbus aucuparia sp	Plant in verge o/s 93 (same position as felled tree)	Crataegus laevigata 'Paul's Sc

FURNISS AVENUE	O/S 83	TR: Felling	Previously topped and stem wounding at crown break, poor structural condition	Prunus Kanzan	Plant in verge o/s 83 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 57-59	TR: Felling	Stem split, poor specimen	Prunus Kanzan	Plant in verge o/s 57-59 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 35-37	TR: Felling	Basal decay, structural integrity in doubt	Prunus Kanzan	Plant in verge o/s 35-37 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 29	TR: Felling	Extensive stem bark necrosis	Prunus Kanzan	Plant in verge o/s 29 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 17	TR: Felling	Extensive stem bark necrosis and f/w mounding	Prunus Kanzan	Plant in verge o/s 17 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
FURNISS AVENUE	O/S 110	structural integrity (TR: Felling-)	decayed topping point into main stem	Sorbus aucuparia	centrally in verge o/s 110 (same position as felled tree)	Sorbus 'schouten'